

TECHNICAL DATASHEET

REFERENCE :

E6200

Old référence :

ALUMINIZED GAITERS CLOSING BY SELF-GRIPPING Description : made of aluminized para-aramid fabric 500g / m²- Unlined - Velcro closingstrap to hold under the sole (this strap is made to easily break in case of hanging to avoid a fall) Formable metal bar to bend before the first use to fit the roundness of the top of the footto prevent the gaiter from turning even in the absence of the strap Very light gaiters - advised for extended wear - all KEVLAR® wire seams E6200-030 : High 42 cm Dimensions : 36cm Sizes availaible_Unique Protection of ankles and feet against thermal hazards (radiant heat and molten metal splashes) - the aluminized coat must cover about 10cm to create a tile effect and prevent projections from penetrating

The materials of this article do not contain any substance that can harm the health of the user

This PPE is in conformity with the requirements of the Directive 89/686/CEE. PPE class III, AET N°033/2017/0373CENTEXBEL

The CE marking on these items means the respect for the essentials requirements of European Directive on PPE based on the standard ISO 13688:2013



A1 B1 C3 D3 E3 F0

ISO 11612:2015

A Limited flame spread	
B Convective Heat	(1 à 3)
C Radiant Heat	(1 à 4)
D Projection of molten aluminium	(1 à 3)
E Projection of molten iron	(1 à 3)
F Contact Heat	(1 à 3)

Use only within the risks covered above

XXXXX Maintenance :

A dirty clothe may cause a reduced protection/

no washing advised, do clean with a damp sponge

Storage : Protected from the light and in a dry place, free of moisture, oils, greases...

Recommandation :

to ensure optimum protection, this equipment must be the complement of appropriate PPEs (shoes, coat, aprons, gloves,

R ()	Coat/Apro	n		
- X	Lenght	Α	Sizes	B et C
A	120 cm	164-170 cm	S – T2	92-96 cm
1 70	130 cm	170-182 cm	M – T3	96-104 cm
	140 cm	182-188 cm	L – T4	104-112 cm
	150 cm	188-194 cm	XL – T5	112-120 cm
	160 cm	194-200 cm	XXL – T6	120-128 cm

For coveralls, take the greatest size between **B** or **C**. The measures must be taken on the person wearing his work clothes, because this equipment is worn over. In doubt between two sizes choose the larger one.