



TECHNICAL DATASHEET

REFERENCE : E5110 & E5111

Old référence :

Description :

ALUMINIZED HOOD
made of aluminized fiber-para-aramid - 100% flame retardant cotton lining Proban® 330g / m2. Adjustable integrated ironmaker helmet (Schuberth Bop / Vulcain Centurion / MSA Thermalguard) -cover unlined shoulders or breastplate 5110-XXX: visor in TRIPLEX 220x100 or 250 x150 metallized OR colorless 5111-XXX: of a visor polycarbonate 250x150 (1 visor colorless of 3mm thickness + 1 golden visor of 1mm thick) or 250x500x1mm metallized GOLDmesh visor in addition to some models- the models foreseen for fire interventions include a protrusion for the valve at the request of the ARI - exists with plastron

Dimensions :

Sizes available adjustable helmet

Protection against fire, radiant heat and splashes of molten metal. CAUTION: Clear visors do not protect against infrared radiation



Recommandation

The materials of this article do not contain any substance that can harm the health of the user

This PPE is in conformity with the requirements of the Directive 89/686/CEE.
PPE class III, AET N°033/2022/0520CENTEXBEL

The CE marking on these items means the respect for the essentials requirements of European Directive on PPE based on the standard ISO 13688



A1 B1 C3 D3 E3 F1

ISO 11612

- A** Limited flame spread (1 à 3)
- B** Convective Heat (1 à 4)
- C** Radiant Heat (1 à 4)
- D** Projection of molten aluminium (1 à 3)
- E** Projection of molten iron (1 à 3)
- F** Contact Heat (1 à 3)

Use only within the risks covered above


Maintenance :

A dirty clothe may cause a reduced protection/ no washing recommended, clean with a damp sponge

Storage : Protected from the light and in a dry place, free of moisture, oils, greases...

Recommandation :

this equipment must be completed with appropriate PPE (coat, gaiters, gloves)



Coat/Apron

Lenght	A	Sizes	B et C
120 cm	164-170 cm	S – T2	92-96 cm
130 cm	170-182 cm	M – T3	96-104 cm
140 cm	182-188 cm	L – T4	104-112 cm
150 cm	188-194 cm	XL – T5	112-120 cm
160 cm	194-200 cm	XXL – T6	120-128 cm

For coveralls, take the greatest size between **B** or **C**. The measures must be taken on the person wearing his work clothes, because this equipment is worn over. In doubt between two sizes choose the larger one.